



2009226

NON-HAZARDOUS WASTE MANIFEST

Please print or type (Form designed for use on elite (12 pitch) typewriter)

NON-HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. <i>UTR 000 000 661</i>		Manifest Document No. <i>090517</i>		2. Page 1 of 1							
3. Generator's Name and Mailing Address <i>USEPA REGION 8 ATTN FLOYD NICHOLS 999 18TH ST.</i>													
4. Generator's Phone (<i>303</i>) <i>512 6983</i> <i>DENVER, CO. 80202-2466</i>													
5. Transporter 1 Company Name <i>MP ENVIRONMENTAL</i>		6. US EPA ID Number <i>CAT 000 624 247</i>		A. State Transporter's ID <i>N/A</i>		B. Transporter 1 Phone <i>877-800-5111</i>							
7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID		D. Transporter 2 Phone							
9. Designated Facility Name and Site Address <i>CLEAN HARBORS GRASSY MOUNTAIN FACILITY 3 MILES EAST 7 MILES NORTH OF EXT 41 OFF I80 CLIVE, UT 84043</i>		10. US EPA ID Number <i>UTO 991 301 748</i>		E. State Facility's ID <i>N/A</i>		F. Facility's Phone <i>801 323-8900</i>							
11. WASTE DESCRIPTION				12. Containers		13. Total Quantity							
a. <i>1' RQ' ASBESTOS, 9, NA 2212, PG-III</i>				No. <i>001</i> Type <i>CM</i>		Unit <i>00025 CT</i>							
b.													
c.													
d.													
G. Additional Descriptions for Materials Listed Above <i>11A) CH-656348 1x25 TO ROLL-OFF #5739 (ASBESTOS CONTAMINATED PRE + ITEMS WETTED + DOUBLE BAGGED) SALES ORDER: D9786345</i>				H. Handling Codes for Wastes Listed Above <table border="1"> <tr><td>CR</td><td></td></tr> <tr><td>FS</td><td><i>AM</i></td></tr> <tr><td>OFFC</td><td></td></tr> </table>				CR		FS	<i>AM</i>	OFFC	
CR													
FS	<i>AM</i>												
OFFC													
15. Special Handling Instructions and Additional Information <i>USE STANDARD PROTECTIVE CLOTHING + EQUIPMENT IN CASE OF EMERGENCY CONTACT (888) 914-7477 24 HR</i>													
16. GENERATOR'S CERTIFICATION: I hereby certify that the contents of this shipment are fully and accurately described and are in all respects in proper condition for transport. The materials described on this manifest are not subject to federal hazardous waste regulations.													
Printed/Typed Name <i>CRAIG MYERS FOR FLOYD NICHOLS</i>				Signature <i>Craig Myers</i>		Date Month <i>05</i> Day <i>17</i> Year <i>04</i>							
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>Deed Anderton</i>		Date Month <i>05</i> Day <i>17</i> Year <i>04</i>							
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date							
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of the waste materials covered by this manifest, except as noted in item 19.													
Printed/Typed Name <i>Ashley Maestas</i>				Signature <i>Ashley Maestas</i>		Date Month <i>05</i> Day <i>20</i> Year <i>04</i>							

NON-HAZARDOUS WASTE

GENERATOR

TRANSPORTER

FACILITY



LOAD SUMMARY RECORD

GM 5083

LOAD DISPOSAL DESTINATION						
<input type="checkbox"/> STABILIZATION	<input checked="" type="checkbox"/> RCRA CELL 7	<input type="checkbox"/> TSCA CELL	<input type="checkbox"/> SPOT STABILIZATION			
LOAD TRACKING INFORMATION						
PLANT RECEIVED	DROPPED	FINAL CODE	REVIEWED	WEIGHTS	GRIDS	MANIFEST MAILED
		a		10	10	
DATE 5/20/04			LOAD NO. 7004007020			
GENERATOR USEPA REGION			HAULER MP			
ORDER NO. D97B6345			DRUM NO. 5305028			
TRUCK NO. 584-		CONTAINER NO. (s)/ RAILCAR NO. 5382				
CONTAINER TYPE: ED (G) TT FB V OTHER				LOAD COUNT (RAIL ONLY): 1 2 3 4		
OPERATOR SIGNATURE				COUNT		DATE

12:33 PM 05 20 04
44440 1b

10:40 05 20 04
44440 1b (H)
41560 1b TARE
2880 1b NET

LOAD WASHOUT INFORMATION		WASHOUT STAMP
WASHOUT:	TYPE:	
YES NO	INTERIOR EXTERIOR	
WASHOUT SIGNATURE	DATE	
DRIVER SIGNATURE	DATE	

ITEM	COMMENTS	NAME	DATE

Clean Harbors Grassy Mountain Facility, Tooele County, Utah

WHITE - Facility

CANARY - Generator

PINK - Transporter

GREEN - Receiving

GOLD - Operations